

FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6






FIG. 8



20220720" E65E/001

FIG. 9



10073593.021202

FIG. 10

URL

TROUBLE DB INPUT EINDOW

OCCURRENCE DATE ~ 404

TYPE OF APPARATUS ~ 401

OBJECT ~ 403

DEVICE S/N ~ 402

DEGREE OF URGENCY ~ 405

SYMPTOM ~ 406

REMEDY ~ 407


PROGRESS ~ 408

410

411

412

20021201 10073593 021201

FIG. 11

SEMICONDUCTOR DEVICE MANUFACTURING FLOW

FIG. 12




FIG. 13




FIG. 14




FIG. 15